performed by vehicles travelling in a forward direction, creating the maximum visibility for these vehicles leaving this site.

3. Additionally, in the Freedom of Information request (3055100/NS/TM5-1/DEHG) the raw traffic survey data used to provide the average speed figure of 45mph and the location that this data was collected at were requested.

The location that the data was collected was provided as "beside a telegraph pole at approximate grid reference NS908774." It was also noted that this location is "within the 40mph speed limit" – see Appendix A.

The proposed vehicular access is within the 30mph speed limit and as such, average traffic speeds taken within a 40mph speed limit would be expected to be higher than the 30mph speed limit. In fact, it would be difficult to propose that traffic readings taken within a 40mph speed limit would be relevant to traffic speeds within a 30mph speed limit.

Observing traffic onsite at the proposed vehicular access within the 30mph limit, it can clearly be seen that:

- Traffic traveling westbound travels slowly uphill towards the brow of the hill and only begins to accelerate again once at the 40mph speed limit sign, which is beyond the proposed vehicular access.
- Traffic traveling eastbound downhill slows as it approaches the 30mph sign due to
 visibility for eastbound traffic being restricted to approx. 70m around the downhill
 curve. This ensures that traffic travelling eastbound slows upon approach to the
 proposed vehicular access.

Reading the 2 pages which detail the Speed Summary (All Days) tables for the raw data taken from the traffic survey data:

- From 08/06/2009 to 14/06/2009 Appendix B
 - o The highest recorded Mean Ave. figure is 36.4mph Speed Limit is 40mph.
- From 07/04/2011 to 14/04/2011 Appendix C
 - o The highest recorded Mean Ave. figure is 34.6mph Speed Limit is 40mph.

Both these maximum recorded mean average figures indicate that even within the 40mph speed limit, vehicles are not travelling at excessive speeds. In fact, westbound traffic has barely begun to speed up after leaving the 30mph limit and, eastbound traffic can easily lower it's speeds to lower limits as it has clear visibility of the 30mph zone and distance to decrease its speed within.

This shows that traffic surveys taken within the 40mph speed limit, in excess of 100m away from the proposed vehicular access still show slow speeds which would allow safe vehicular access to be created onto Shieldhill Road.

Summary

In summary, we believe that the proposed vehicular access can be safely constructed in line with Falkirk Roads Development unit design standards, based upon:

- Shieldhill Road is already an extremely safe road, with zero recorded accidents in the last 3
 years.
- Visibility, both East and West bound, can be shown to exist in excess of 70m, as required by Falkirk Roads Development unit.
- Average speeds in the 40mph limit, in excess of 100m away from the proposed access, are
 well within the 40mph speed limit and provide substantial distance for vehicles to further
 reduce their speeds before approaching the 30mph limit that the access would be within.

ROADS & DESIGN
Enquiries to: Duncan Gardner
Tel No: 01324 504636
Fax No: 01324 504843



Roy Donalds

Out Ref: 3055100/NS/TM5-1/DEHG Your Ref:

04 May 2011

Dear Mr Donalds,

Accident and Traffic Data Request - B810, Shieldhill Road

I refer to your Freedom of Information enquiry received in this office on 18 April 2011 regarding the above.

I can advise you that the available data indicates that there have been no recorded personal injury accidents on Shieldhill Road between Shieldhill and Reddingmuithead during the last 3 years.

With regard to your request for all traffic survey data taken on the B810 between Shieldhill and Reddingmulrhead please find attached data from 2009 and 2011.

The location of where the survey was taken beside a telegraph pole at approximate grid reference NS908774 which is within the 40mph speed limit.

Please refer to the enclosed leaflet which explains your right to complain about the handling of your case and/or the decision made.

Yours sincerely

Duncan Gardner Network Officer

Director: Blayer Gento

Aldenstord House, Darbh Luan, Edbirl IEC WZ I b I Takirl J Telephone: ULIZI 504950

Adolf Morania

110428/dchg

CR43055100

Appendix 4

				100													
ite No: 20	090110		· .				*							S	le Refer	ence: 20	09011
								III Rd. RJ 06/2009			in St.				7		-67 I
ecd Sur	nmary (All Dava)-Limit 4	Moh			Lion où	のめてハハン	10 10/01	NZ463	3.						
Seso Repos	रक्ते रहा	236) 544	Eran Air.	\$≥ <u>±</u> [474	E±1 ctules	Las it-ets	B+13 16-431	En4 21-06	Ba5 25-01	31-436	En 7-	En≇ £1.446	(219 47-45)	En 17	En 11 M→si	All Ci	ianne En
0.90	39	25.2	31.8	6.5		e	ð.	3	33	11		,		•		:	· .
₹#Ó \$£\$\$	73 11	33.1 27.3	23.1	\$_5	.0	16	9	¢		6	- 4	- 1	č	-3	.0	è.	
3.93	to	33.1	34.5	4.7	ð.	. 0		2	3	:	3.	Ç	0	p	ō	ē	
1,(5)	Ē		2.4	6.1	ě	ě	é	õ	ž	3		8	, v	9	ě	ş	
୫ ଜନ୍ମ ୧୯୯୬	51	40.5	35.9			: 2	8.	ė	÷	7	ě	3	•	2			
7.52	57 378	41 <u>.5</u> 75.5	22.3	€,1	\$	ě	•	3	15	23	2.4	7	3	ž	ă	ä	
\$30	714	35.4	2 <u>1</u> 1	22.55.25.45.5 5.55.25.45.5 5.55.25.45.5	똰	¢	€.	9	*4	76	3.6	*	ź	ũ	ő	6	
400	722 726 725	26.5	21.3	-55	Ŷ	: 27	•	7	154	12E	37	€	Ç	¢	ō	õ	
10.99	2.55	25.5	311	52	3	1	3	.17 21	74 £3	13	78	4	ę.	Q	Ò	Ġ.	
10.97	225	352	39.9	58	ৰ ব	- 1	ž	41	25	13	25		£	ō	ō	ø	
1220	215	35.5	31.7	£.5	É		- 2	25 25	57	12	2.0	2		Đ	g.	0	
13 00	244	36.6	21.2	5.5	ě.		É	26 28	Ŷ.	ii	34	7	Ÿ	Ž,	5	õ	
1400	231	28.5	***	5.9	₽	2	6	24	#5	. 75	27	Ś	- 5	ñ	Ä	,	
15-07	315	34.1	20 F :	5.5		ŧ	. 2	24	125	164	24	ŧ	ä	p	ň	ň	
17.53	353	27,4	21.7	5 4	- E	•	: 25	24	£15	179	47		Í	ñ	õ	ě	
12.50	283	312	32.0 33.7	5.8	3	18	7 2	75 14	111	123	54	*1	3	6	ò	ō	
15.60	2:0	353	22,A	5.2		1	2	15 E)	55 25	21	\$1 32	.13	4	9	6	ō	
2350	145	37.4	32.5 72.5	4.2 5.5	7			15	:61	73	3.5	7.	- 72	9	¢.	ø	
2101	1.52	342	72 £	5.5	ě	·å	é	÷	- 46	4-3	20 25	*		.5	e		
22 00 23 00	54 ±5	31.4	32.0	2.2			Ç	12	25	27	₩.	š	ė.	ñ	ž		
2333	- 45	₹ €	32.5	5.5	ত	∵ē	. 6	. 3	. 1 5	(≑	٦.	3.	ė	ē	÷	Ď	
ZH, 7-12	3163	16.5	21.5 31.1 31.1	53		11	52	775	1142	1145	423	. 85	15		c		
516-22 516-24	3243	37.4	35.8	34	3	3.9	5.7	775 312	1331	3777	531	114	74	*	Ž.	ė	
21034	2512	31.3	31.7 31.E	5.4 5.4		12	52 52 52 53	274	1299	1425	322	172	24	. 5	ë	Ó	
A-3	115	***	400	£ (€	11.29	£30	-22 10:35	327 10.35	₹422 ₹.15	1635 £ 15	\$27 8.90	127 .0.15	20	2	p	Đ	
Feet	\$35		25.4	0.7	17	Ŧ	1935	74	137	119	\$. \$	19	£30 4	545	£33	÷.	
Fan Peak	1(3) NS	22.65 18.5	20,43	21.34	1563	1446	\$4.45	15.15	11.00	15-53	16.45	17.15	11.00	15.33	15.45	20.15	190
4 444	200	44.2	37_3	. 64	. 2.	3	· · · · · · · · · ·	35	224	147	55	12	7.37	47.7			

.

Printed at 10:03:05 on 28 Apr 2011

Appendix 2

Site No: 20	110100													Sit	a Refer	nce: 201	110100
					Lir	ık 441 SI	rom 07	Rd R/M/ na/2011	Head Ro To 13/04	l to Main V2011	SI SIIII						
Spead Sen	ninary (/	UI Davs	Limit «	Moh				9-92-9-17				>					annels
Tim e Exgin	J#M VeL	1579 1480	Prot	59.1 Det	511 411265	£87.2 11-456	E表 3 15-421	£i54 21≪35	(元)	\$2.5 \$1.436	35-4(t	Ong that	1807 18-151	En 13	En ti	FantZ 61-46	E-11
			311		- 44			,	10	11							
0.00 1.00	33 11	10.5 35.4	312	6.5 5.0	ø	.0	0		6	3	2	į,	å	ž	š	ě	3
266	g		346	54	.0	ą.	6	ŧ	3	2.	•	ú	Đ.	ů.	9	á	•
7.00	*		34.5	50	· o	ě	•	E		à	1		5	8	þ		8
4 (70) 2 (30)	-	39.8	\$9.1 34.5	3.5	ē	ě	•	ŧ	3	13	7	2	2	ž	4	9	
6.55	79 10	57.8 47.8	34.5	7.1 6.0	ů	Ä	,	- 1	20	23	75	õ	ž	ě	Ė	ñ	ě
7:50	177	19.1	23.4	5.4	ě	õ	ò	ě	20) 49	23 45	4.7	1	2	ġ.		ė	ż
8.00 8:00	212	37.3	72.7	5.1	è	Ť	ż	á	iv	- 55	** ** ** **	₹	1	Ŷ	ę	Ė	9
17.0	200	20.4	31.5	5.3	0	1	3	1*	72 13 29	74	35	ē	2	8	\$	9	ě
11:00 11:00	213 251	\$63	211	55 55 53 53	9	- 1	,	22 23 24 25 23 23 24 25 21	57	13 94	- 41		15 N	E e	*	ti n	6
12.50	753	27 /	30.5 31.1	56	1 2	- 5	3	51	£12	96	33	ž.	ŏ	è	ě	ě	ě
13 03	231	357 500 501	213	53	ŏ	õ	- 1	24	154	121	25 35	6	5	ē	5	ø	\$
1695	271	35.1	35.2	5.5 5.5	ð	1	į.	23	200	\$1	35	7	6	Ģ	\$	Đ.	ş
15 00 15 00	253	35.5	31.4	3.5	0	1	7	23	99 110	195	25		ō	ç	9	ē	. 2
15:00	342	27,1	319	55 55 55 55	Ď.		2	23	121	131 144	54. 47.	15 12	;	ž	5	č	š
17.00 17.00	324	- \$7.2 27.3	22.0 32.1	22	4	í	3	53	121	123	42 -	11	ž	Ď	ě	é	é
19-50	255	26.8	21.0	5.5	i	i	5		3-5	121	23		1	¢	ŧ,	ō	ę
22:03	124	2-5.2	315	2.5	Đ	4	ŧ	18	24	25	35			*	4	a	9
\$1.00 52:00	150	35 1	313	27	Ŷ	ō	š	19	56 38	53 53	11	3	2	6	9	9	ě
72:00	#5 .	\$9.3 \$3.5	\$1.5 32.5	5 3 7.5	9	6	5	*	14	15	76	ź	ě	ž	à	ě	à
12.31	7.4	7-7	54.0	1,-2	•	٠	•	•	• • • • • • • • • • • • • • • • • • • •		Ŧ	_	-	-	-	-	-
12:17:19	2243	26.8	31.7	23	3	13	46	219	11(2 12(6	1589 1846	414 654 578	\$1	19	5	4	v	ŧ
15:46-22	2900	24.5	\$1.7	\$3 \$3 \$3 53	4	14	52	256	\$216	122	\$5€	421 129 131		•	9	ç	,
16-16-24 2440-24	4643 4855	36 9 27.0	31.7 31.8	53	1	14	53	31F 323	\$47.8 1+53	1474 1533	554	10	14	ž	ň	ž	į.
44550-25	****	\$4N	47.8	5.9	4	14.	. 53	243	1+33	دوه ر	224			*	*		٠
tes.	1500	i	\$ 25	E 00	10 16	15.00	16:00	15.45	\$150	11:30	7.63	6.35	6.55	10.15	- 5.53	710	•
79.00	251	-	.5.1	7.1	1	\$	ŧ	27	49	95	47	ø	3	Ŷ		•	. *
Fes	6.44	23.00	23.50	72 (0 7.5	12:45	12.33	15.15	27	35.49	35.45	15.45	17.65	17.33	18.30	11.23 0	23.50	73.50 fe
F 1 14	371	15.5	22.5	7.5	.2	2	7	23	\$22	642	<u>#</u> 7	12	2		· p		

Appendix C

2nd August 2011

Falkirk Council Abbotsford House David's Loan Falkirk FK2 7YZ

SCOTTISH WATER

Customer Connections 419 Balmore Road Glasgow G22 6NU

Customer Support Team T: 0141 355 5511 F: 0141 355 5386

W: www.scottishwater.co.uk
E: connections@scottishwater.co.uk

Dear Sir/Madam

(

PLANNING APPLICATION NUMBER: P/11/0465/PPP

DEVELOPMENT: Rumah, Shieldhill Road, Reddingmuirhead, Falkirk, FK2 0DU

OUR REFERENCE: 581663

PROPOSAL: Sub-Division of Plot and Erection of New Dwellinghouse

Please quote our reference in all future correspondence

In terms of planning consent, Scottish Water does not object to this planning application. However, please note that any planning approval granted by the Local Authority does not guarantee a connection to our infrastructure. Approval for connection can only be given by Scottish Water when the appropriate application and technical details have been received.

Carron Valley Water Treatment Works currently has capacity to service this proposed development.

The water network that serves the proposed development is currently able to supply the new demand.

Kinneil Kerse Waste Water Treatment Works currently has capacity to service this proposed development.

Wastewater Network – Our initial investigations have highlighted their may be a requirement for the Developer to carry out works on the local network to ensure there is no loss of service to existing customers. The Developer should discuss the implications directly with Scottish Water.

In some circumstances it may be necessary for the Developer to fund works on existing infrastructure to enable their development to connect. Should we become aware of any issues such as flooding, low pressure, etc the Developer will be required to fund works to mitigate the effect of the development on existing customers. Scottish Water can make a contribution to these costs through Reasonable Cost funding rules.

A totally separate drainage system will be required with the surface water discharging to a suitable outlet. Scottish Water requires a sustainable urban drainage system (SUDS) as detailed in Sewers for Scotland 2 if the system is to be considered for adoption.

Scottish Water's current minimum level of service for water pressure is 1.0 bar or 10m head at the customer's boundary internal outlet. Any property which cannot be adequately serviced from the available pressure may require private pumping arrangements installed, subject to compliance with the current water byelaws. If the developer wishes to enquire about Scottish Water's procedure for

checking the water pressure in the area then they should write to the Customer Connections department at the above address.

If the connection to public sewer and/or water main requires to be laid through land out-with public ownership, the developer must provide evidence of formal approval from the affected landowner(s). This should be done through a deed of servitude.

It is possible this proposed development may involve building over or obstruct access to existing Scottish Water infrastructure. The Developer should discuss the implications directly with Scottish Water.


Should the developer require information regarding the location of Scottish Water infrastructure they should contact our Property Searches Department, Bullion House, Dundee, DD2 5BB. Tel – 0845 601 8855.

If the developer requires any further assistance or information on our response, please contact me on the above number or alternatively additional information is available on our website: www.scottishwater.co.uk.

Yours faithfully

Morven Henderson

Customer Connections Administrator Tel: 0141 355 5289 morven.henderson@scottishwater.co.uk



Morris, John

From:

hillis, alfred

Sent:

05 August 2011 14:53

To:

adtm1dmbscorr

6 1.1. . 4. D/44/0405/DD

Subject: P/11/0465/PPP - Rumah, Shildhill Road, Reddingmuir head.

Contaminated Land

Conditioned due to historic quarries, infilled ground and mineral railways within 250m of the site.

- 1. Unless otherwise agreed in writing no development shall commence on site until a contaminated land assessment in accordance with current guidance has been submitted and approved by the Planning Authority. The assessment shall determine the nature and extent of any contamination on the site, including contamination that may have originated from elsewhere, and also identify any potential risks to human health, property, the water environment or designated ecological sites.
- 2. Where contamination (as defined by Part IIA of the Environmental Protection Act 1990) is encountered, a detailed remediation strategy shall be submitted to and approved in writing by the Planning Authority. The strategy shall demonstrate how the site shall be made suitable for its intended use by the removal of any unacceptable risks caused by the contamination.
- 3. Prior to the commencement of development the remediation works shall be carried out in accordance with the terms and conditions of the remediation scheme as approved in writing by the Planning Authority. No part of the development shall be occupied until a remediation completion report/validation certificate has been submitted to and approved in writing by the Planning Authority.
- 4. In the event that unexpected contamination is encountered following the commencement of development, all work on the affected part of the site shall cease. The developer shall notify the Planning Authority immediately, carry out a contaminated land assessment and undertake any necessary remediation works. Development shall not recommence without the prior written approval of the Planning Authority.

Environmental Health

The applicant requires to use acoustic glazing with a specification of 6/12/6 or acoustic equivalent In order to protect the occupiers of the proposed dwelling from transportation noise which shall ensure that the internal levels with the windows closed do not exceed 45dB daytime and 35dB night-time, when measured as LAeq,T, and permanent ventilation be provided in order that windows can be kept closed without loss of ventilation. The details shall be submitted to, and approved by, the Planning Authority prior to the commencement of construction works.

Alf Hillis
Environmental Health Officer
01324 501024

The information contained in this e-mail is confidential and is intended only for the named recipient(s). If you are not the intended recipient, you must not copy, distribute or take any action or reliance on it. If you have received this e-mail in error, please notify the sender. Any unauthorised disclosure of the information contained in this e-mail is strictly prohibited.

The views and opinions expressed in this e-mail are the senders own and do not necessarily represent the views and opinions of Falkirk Council.

Council.

136

Morris, John

From:

MacKenzie, Roddy

Sent:

29 July 2011 08:27

To: Cc: adtm1dmbscorr Raeburn, Brian

Subject: P-11-0465-PPP Shieldhill Road

Development Services

Memo

To:

David Paterson, Planning Officer

Planning and Transportation (Development Control)

From:

Roddy Mackenzie, Roads Development

Date:

(

29 July 2011

Enquiries: 4908

Fax: 4850

Our Ref: RMK/

Your Ref: P/11/0465/PPP

Proposal : Subdivision of Plot & Erection of New Dwellinghouse

Location: Rumah, Shieldhill Road, Reddingmuirhead, Falkirk, FK2 0DU

Application: P/10/0465/PPP

I refer to your consultation notice received on 12 May 2010 regarding the above application. The site has been subject to a previous application (P/10/0306/PPP) and as the site details are the same, I would comment as follows:-

The proposal would result in a 3 bedroom dwelling with a private driveway which will access directly on to the B810 Shieldhill Road.

Shieldhill Road at this location is a classified semi-rural road with a 30mph speed limit that changes to 40mph to the immediate west of the site. Vehicle speeds can be considerably more than the set limits at times.

This proposed dwelling at the west side of 'Rumah', accessing directly on to Shieldhill Road, would have good visibility to the west but not to the east where there would only be 40m clear visibility to a blind summit. This restricted visibility to the east, could in my view, create a dangerous situation for traffic turning right in to the site and turning right while exiting the site. A dwelling having access on to Shieldhill Road at this location may also lead to vehicles parking on Shieldhill Road itself, adding further to our road safety concerns.

With downhill east-bound vehicle speeds regularly exceeding the speed limits we would not favour any development on this site accessing on to Shieldhill Road due to the impaired visibility and the proximity to the existing blind summit.

Regards.

RMK

The information contained in this e-mail is confidential and is intended only for the named recipient(s). If you are not the intended recipient, you must not copy, distribute or take any action or reliance on it. If you have received this e-mail in error, please notify the sender. Any unauthorised disclosure of the information contained in this e-mail is strictly prohibited.

The views and opinions expressed in this e-mail are the senders own and do not necessarily represent the views and opinions of Falkirk Council.

Development Services

Memo

To:

David Paterson, Planning Officer

Planning and Transportation (Development Control)

From:

Roddy Mackenzie, Roads Development

Date:

08 Sept 2011

Enquiries: 4908

Our Ref: RMK/

Your Ref: P/11/0465/PPP

Proposal :

: Subdivision of Plot & Erection of New Dwellinghouse

Location : Rumah, Shieldhill Road, Reddingmuirhead, Falkirk, FK2 0DU

Application: P/10/0465/PPP

I refer to your consultation notice received on 12 May 2010 regarding the above application and the applicants supporting statement in particular.

1. Visibility to the east

The supporting statement states, that from the proposed access to the site east along Shieldhill Road, a visibility splay of 2.5m x 76m is achievable. This is not the case. For any avoidance of doubt we measured the visibility from the proposed site yet again, and to try and make things completely clear, recorded the results with photographs (see attachment 1). The supporting statement also states that a visibility splay should take the curvature of a road in to account. Again this is wrong. A visibility splay is taken from the proposed access to the furthest point on the nearer edge of the major road carriageway channel that one can see (see attachment 2). The 'y' measurement in this case was found to be 47.7m. We also went on to show photos of the view of our operative with staff at 78m at the south channel of the road as shown on the applicants drawing (see attachment 3), then at 70m and then 60m (the operative is only in view at 60m as she moved a metre or so out from the road channel). The visibility splay as shown by the applicant is taken to the wrong side of the road and the actual visibility claimed cannot be achieved on site.

2. Safety Record

When the applicants FOI request for accident data was replied to, the fact that there were no recorded personal injury accidents for the last 3 years, may well have been correct. We now have a more up to date and more complete picture of the accident statistics (see attachment 4) and they show that since 1987 there have been a total of 8 personal injury accidents, 5 slight and 3 serious (all within 75m of access road to Rumah). These statistics show that the accident severity ratio of 37.5% is almost 50% more than the normal ratio of 26%. There has also been 1 non injury accident recorded at the location. So there have been 8 accidents in 24 years with a high accident severity ratio. The road safety concerns about this location cannot be ignored.

3. Traffic Survey Data

The traffic survey data provided to the applicant in the FOI was taken on Reddingmuirhead Road/Shieldhill Road but not at the specific location that the applicant states, i.e. at a telegraph pole to the west of Rumah. The Traffic Survey in the support statement was part of the bi-annual programme of traffic counts and could have been taken at any point on that particular section of road. It is not known exactly where on the B810 these speed statistics were taken and so they should be disregarded.

I have the actual data taken at the location to which the applicant refers, approximately 100m to the west of the site in the 40mph limit area between 23 June 2010 and 29 June 2010 (see attachment 5). This survey provided the actual speed of cars coming downhill towards the proposed site from Shieldhill and the 85th%ile speed was found to be 45mph. The 85th%ile speed is used when determining visibility requirements for roads calculations. The applicant uses the Mean Average speed to argue his case, which is not appropriate.

To be consistent I also had a traffic survey carried out directly adjacent to Rumah itself within the 30mph limit and it was found that the 85th%ile for westbound traffic was 42.4mph and for eastbound was 40.0mph. This clearly shows that most vehicles are travelling at least 33% faster than the legal speed limit at a blind summit. This is not, therefore, a location where any extra manoeuvring, overtaking, parking, or queuing on the road to turn right, should for road safety reasons be encouraged.

4. Summary

From a roads point of view, the applicants supporting statement does not change our opinion and most points that the applicant refers to have to be disregarded as I have shown. I would again reiterate that I am still of the opinion that a new access at this location, with poor visibility to the east only 40m from a blind summit, is not acceptable. With the added complication of vehicles turning right into or out of the site, and vehicles parked on the main road, the road safety hazards at that location would be increased significantly. Therefore, our road safety concerns could be used to support a recommendation of refusal.

Regards.

RMK


Rumah, Shieldhill Road 09/08/11




Visibility east at proposed access 30m back from private road




Visibility splay 47.7m from proposed access




Visibility to 78m from proposed access (view hidden)




Visibility to 70m from proposed access (view still hidden)



Visibility to 60m from proposed access (in view but out from channel)





"Full Details Report Summary - B810 within 75m of direct access to Springbank Cottage

Accidents Found Date Range: 29/07/1987 - 18/03/2011 Grid Coordinate Range: 290900,677500-291000,677570

Neither accuracy nor completeness of the data herewith is guaranteed Accident Severity

	1987	1988	1990	2011	Total
Serious	1	1	0	1	3
Slight	1	2	1	1	5
Total	2	3	1	2	8

Total =
$$\frac{0+3}{8} = 0.375$$

Casualty Severity

	1987	1988	1990	2011	Total
Serious	1	1	0	1	3
Slight	2	4	2	1	9
Total	3	5	2	2	12

Casualty KSI

	1987	1988	1990	2011	Total
Adult KSI	1	1	0	1	3
Slight	2	4	2	1	9
Total	3	5	2	2	12

${\tt B810}$ within 75m of direct access to Springbank Cottage

1.3 Accident Reference: 87UG15096 Serious B810 AT JN FOR S	PRINGBANK COTTAGE, REDDINGMUIRHEAD Acci	dent 1 of 8
1.7 Date & 1.9 TimeWednesday 29/07/1987 13:15 1.11 Grid co-ordinates290930/677540 1.10 Local AuthorityFalkirk 1.12/1.13 1st road identity.B810 1.18/1.19 2nd road identity.U 1.22 WeatherFine 1.21 Light conditionsLight/no lights 1.20a Crossing(human)No Human control within 50m 1.20b Crossing(physical)No crossing facility within 50m	1.15 Speed limit30 Mph 1.14 Road typeSingle c'way 1.16 Junction detailUsing private driv 1.17 Junction controlGive way sign or v 1.24 Special conditionsNone 1.25 Carriageway hazardsNone 1.5 Number of vehicles2 1.6 Number of casualties.1 1.23 SurfaceDry	ve or entranc incontrolled
Contributory Factors	Participant Confidence	Did a police

Accident Description

LORRY TURNING FROM WEST TO NORTH, FROM WRONG SIDE OF ROAD, COLLIDED WBD CAR

2 Vehicles	
2.4 Veh ref no	2.16 First impactFront 2.12 Hit object in c'way. None 2.14 Hit object off c'way. None 2.18 Parts damaged/ / Front 2.21 Driver genderMale 2.22 Driver age44 2.27 Driver postcode 2.24 Hit and RunNo 2.23 Breath testNot requested 2.29 Journey purpose
2.4 Veh ref no2 2.17 Other vehicle1 2.5 Vehicle classCar 2.10 Junction locationMid junction 2.9 Restricted location.On main carriageway 2.8 Movement from/toEast West 2.7 ManoeuvresGoing ahead left hand bend 2.11 SkiddingYes 2.13 Left c'wayDid not leave c'way 2.6 TowingNo 2.28 Foreign vehicleNot foreign	2.16 First impactFront 2.12 Hit object in c'way. None 2.14 Hit object off c'way. None 2.18 Parts damaged / / Front 2.21 Driver genderMale 2.22 Driver age45 2.27 Driver postcode 2.24 Hit and RunNo 2.23 Breath testNot requested 2.29 Journey purpose
1 Casualty	
3.5 Cas ref no1 3.6 Casualty classDriver or Rider 3.7 Gender	3.15 Car passengerNo 3.16 PSV passengerNo 3.14 Seat belt usage 3.13 School pupilOther (3.19 School) 3.10 Pedestrian locationNot a pedestrian 3.11 Pedestrian movementNot a pedestrian 3.19 Roadworker injuredNo

B810 within 75m of direct access to Springbank Cottage

ADJUSTED AFTER PO 1.7 Date & 1.9 TimeFriday 18/12/1987 17:30	WEST OF FAIRHAVEN TERRACE (CO-ORDS Accident 2 of 8 LICE RESPONSE TO QUERY) 1.15 Speed limit30 Mph
1.11 Grid co-ordinates290940/677550 1.10 Local AuthorityFalkirk 1.12/1.13 1st road identityB810 1.18/1.19 2nd road identity	1.14 Road typeSingle c'way 1.16 Junction detailNot at or within 20m of juncti 1.17 Junction control
1.22 WeatherOther 1.21 Light conditionsLight/with lights 1.20a Crossing(human)No Human control within 50m 1.20b Crossing(physical)No crossing facility within 50m	1.24 Special conditionsNone 1.25 Carriageway hazardsNone 1.5 Number of vehicles2 1.6 Number of casualties.2 1.23 SurfaceWet
Contributory Factors	Participant Confidence Did a police officer attend

Accident Description CAR TRAVELLING WE

CAR TRAVELLING WEST TO EAST COLLIDED WITH CAR PARKED OF	N NORTHSIDE OF ROAD FACING EAST AND WITH HAZARD LIGHTS	ON.
2 Vehicles		
2.4 Veh ref no	2.16 First impactFront 2.12 Hit object in c'way.None 2.14 Hit object off c'way.None 2.18 Parts damaged/ / Front 2.21 Driver genderMale 2.22 Driver age34 2.27 Driver postcode 2.24 Hit and RunNo 2.23 Breath testNot requested 2.29 Journey purpose	(
2.4 Veh ref no	2.16 First impactBack 2.12 Hit object in c'way.None 2.14 Hit object off c'way.None 2.18 Parts damaged/ / Back 2.21 Driver genderMale 2.22 Driver age	
2 Casualties		
3.5 Cas ref no	3.15 Car passengerNo 3.16 PSV passengerNo 3.14 Seat belt usage 3.13 School pupilOther (3.19 School) 3.10 Pedestrian location.Not a pedestrian 3.11 Pedestrian movement.Not a pedestrian 3.19 Roadworker injuredNo	(
3.5 Cas ref no2 3.6 Casualty classPassenger 3.7 Gender	3.15 Car passengerFront 3.16 PSV passengerNo 3.14 Seat belt usage 3.13 School pupilOther (3.19 School) 3.10 Pedestrian location.Not a pedestrian 3.11 Pedestrian movement.Not a pedestrian 3.19 Roadworker injuredNo	

B810 within 75m of direct access to Springbank Cottage

1.3 Accident Reference:88UG14102 Serious B810 ABT 200YDS	WEST OF JN NOBEL VIEW Accident 3 of 8
1.7 Date & 1.9 TimeSunday 05/06/1988 11:20 1.11 Grid co-ordinates290900/677500 1.10 Local AuthorityFalkirk 1.12/1.13 1st road identity.B810 1.18/1.19 2nd road identity. 1.22 WeatherFine 1.21 Light conditionsLight/unknown 1.20a Crossing(human)No Human control within 50m 1.20b Crossing(physical)No crossing facility within 50m Contributory Factors	1.15 Speed limit30 Mph 1.14 Road typeSingle c'way 1.16 Junction detailNot at or within 20m of juncti 1.17 Junction control 1.24 Special conditionsNone 1.25 Carriageway hazardsNone 1.5 Number of vehicles1 1.6 Number of casualties.2 1.23 SurfaceDry
Contributory Pactors	Participant Confidence Did a police officer attend
Accident Description	
WBD CAR DRIVER LOST CONTROL, LEFT ROAD, HIT TELEGRAPH POLE	ON NORTH SIDE OF ROAD.
1 Vehicle	
2.4 Veh ref no1 17 Other vehicle0 5 Vehicle classCar 2.10 Junction locationNot at junction 2.9 Restricted location.On main carriageway 2.8 Movement from/toEast West 2.7 ManoeuvresGoing ahead left hand bend 2.11 SkiddingNo	2.16 First impactFront 2.12 Hit object in c'way. None 2.14 Hit object off c'way. Telegraph/electricity pole 2.18 Parts damaged//Front 2.21 Driver genderFemale 2.22 Driver age
2.13 Left c'wayLeft c'way Offside 2.5 TowingNo 2.28 Foreign vehicleNot foreign	2.24 Hit and RunNo 2.23 Breath testNot requested 2.29 Journey purpose
2 Casualties	
3.5 Cas ref no1 3.6 Casualty classDriver or Rider 3.7 GenderFemale 3.8 Age19 3.18 Casualty postcode 3.9 SeveritySlight 3.4 Vehicle no1 3.12 Ped DirectionNot a pedestrian	3.15 Car passengerNo 3.16 PSV passengerNo 3.14 Seat belt usage 3.13 School pupilOther (3.19 School) 3.10 Pedestrian location.Not a pedestrian 3.11 Pedestrian movement.Not a pedestrian 3.12 Roadworker injuredNo
3.5 Cas ref no2 3.6 Casualty classPassenger 3.7 GenderMale 3.8 Age19 3.18 Casualty postcode 3.9 SeveritySerious 1 Vehicle no1 1.12 Ped DirectionNot a pedestrian	3.15 Car passengerFront 3.16 PSV passengerNo 3.14 Seat belt usage 3.13 School pupilOther (3.19 School) 3.10 Pedestrian locationNot a pedestrian 3.11 Pedestrian movementNot a pedestrian 3.12 Roadworker injuredNo

B810 within 75m of direct access to Springbank Cottage

1.3 Accident Reference: 88UG15142 Slight B810 ABT 400 YDS	WEST OF JN NOBEL VIEW	Accident 4 of 8
1.7 Date & 1.9 TimeTuesday 09/08/1988 12:30 1.11 Grid co-ordinates290930/677540 1.10 Local AuthorityFalkirk 1.12/1.13 1st road identity.B810 1.18/1.19 2nd road identity 1.22 Weather	1.15 Speed limit	way or within 20m of juncti
Contributory Factors	Participant Co	nfidence Did a police officer atten
Accident Description		CIDE SYIDDED MADAGE DANG
CAR TRAVELLING WEST TO EAST ON RIGHT HAND BEND WHEN DRIVER AND CAME TO REST ON NORTH FOOTWAY.	LOST CONTROL, MOUNTED BANK ON SOUTH	SIDE SKIDDED ACKOSS KOAD
Vehicle		
2.4 Veh ref no1 2.17 Other vehicle0 2.5 Vehicle classCar 2.10 Junction locationNot at junction 2.9 Restricted location.On main carriageway 2.8 Movement from/toWest East 2.7 ManoeuvresGoing ahead right hand bend 2.11 SkiddingYes & Overturned 2.13 Left c'wayLeft c'way offside and rebounded 2.6 TowingNo 2.28 Foreign vehicleNot foreign	2.16 First impactFront 2.12 Hit object in c'way. None 2.14 Hit object off c'way.Other policy 2.18 Parts damaged/ / A 2.21 Driver genderMale 2.22 Driver age18 2.27 Driver postcode 2.24 Hit and RunNo 2.23 Breath testNot req 2.29 Journey purpose	ll 4 sides
2 Casualties		
3.5 Cas ref no	3.15 Car passengerNo 3.16 PSV passengerNo 3.14 Seat belt usageOther (3.13 School pupilOther (3.19 School) 3.10 Pedestrian location.Not a pe 3.11 Pedestrian movement.Not a pe 3.19 Roadworker injuredNo	
3.5 Cas ref no2 3.6 Casualty classPassenger 3.7 GenderMale 3.8 Age17 3.18 Casualty postcode	3.15 Car passengerFront 3.16 PSV passengerNo 3.14 Seat belt usage 3.13 School pupi1Other (3.19 School)	

(3.19 School)

3.10 Pedestrian location. Not a pedestrian 3.11 Pedestrian movement. Not a pedestrian 3.19 Roadworker injured...No

3.18 Casualty postcode...
3.9 Severity......Slight
3.4 Vehicle no......1
3.12 Ped Direction.....Not a pedestrian

B810 within 75m of direct access to Springbank Cottage

1.3 Accident Reference:88SG12214 Slight B810 ABT 1/2 M	ILE WEST OF REDDINGMUIRHEAD ROAD	Accident 5 of 8
1.7 Date & 1.9 TimeSunday 20/11/1988 15:30 1.11 Grid co-ordinates290950/677550 1.10 Local AuthorityFalkirk 1.12/1.13 1st road identity.B810 1.18/1.19 2nd road identity 1.22 WeatherFine 1.21 Light conditionsLight/unknown 1.20a Crossing(human)No Human control within 50m 1.20b Crossing(physical)No crossing facility within 50m	1.15 Speed limit30 Mph 1.14 Road typeSingle c'way 1.16 Junction detailNot at or within 20m of juncti 1.17 Junction control 1.24 Special conditionsNone 1.25 Carriageway hazardsNone 1.5 Number of vehicles2 1.6 Number of casualties.1 1.23 SurfaceDry	
Contributory Factors	Participant Com	fidence Did a police officer atter
•		
•		
·		
Accident Description	And the second of the second o	DI DETOUR ARRITAGER
VAN TRAVELLING EAST TO WEST STRUCK STATIONARY CAR PARKED	ON NEARSIDE. DRIVER'S VISION OBSCURED	BI BRIGHT SUBLIGHT .
2 Vehicles		
2.4 Veh ref no1		
.17 Other vehicle2	2.16 First impactFront	
5 Vehicle classGoods < 3.5t	2.12 Hit object in c'way. Parked vehicle unlit	
2.10 Junction locationNot at junction	2.14 Hit object off c'way.None	
2.9 Restricted location.On main carriageway	2.18 Parts damaged / / Fr 2.21 Driver genderMale	ont
2.8 Movement from/toEast West	2.22 Driver age1	·
2.7 ManoeuvresGoing ahead other	2.27 Driver postcode	
2.11 SkiddingNo 2.13 Left c'wayDid not leave c'way	2.24 Hit and RunNo	
2.6 TowingNo	2.23 Breath testNot requested	
2.28 Foreign vehicleNot foreign	2.29 Journey purpose	
2.4 Veh ref no2		
2.17 Other vehicle1	2.16 First impactBack	
2.5 Vehicle classCar	2.12 Hit object in c'way. None	
2.10 Junction locationNot at junction	2.14 Hit object off c'way.None 2.18 Parts damaged/ / Ba	ck
2.9 Restricted location.On main carriageway 2.8 Movement from/toParked	2.21 Driver genderFemale	
	2.22 Driver age35	
2.7 ManoeuvresParked	2.27 Driver postcode	
2.11 SkiddingNo 2.13 Left c'wayDid not leave c'way	2.24 Hit and RunNo	
2.6 TowingNo	2.23 Breath testNot requ	iested
2.28 Foreign vehicleNot foreign	2.29 Journey purpose	
1 Casualty		
3.5 Cas ref no1	3.15 Car passengerFront	
3.6 Casualty classPassenger	3.16 PSV passengerNo	
7 GenderFemale	3.14 Seat belt usage	
.8 Age62	3.13 School pupilOther	
3.18 Casualty postcode	(3.19 School)	
3.9 SeveritySlight	3.10 Pedestrian location. Not a pedestrian	
3.4 Vehicle no2	3.11 Pedestrian movementNot a pedestrian 3.19 Roadworker injuredNo	
3.12 Ped DirectionNot a pedestrian	5.15 ROBUNDING! Injured: 1.10	

1:52

B810 within 75m of direct access to Springbank Cottage

1.3 Accident Reference: 90UG12631 Slight B810 ABOUT 200	YDS WEST OF JN NOBEL VIEW .	Accident 6 of 8	
1.7 Date & 1.9 TimeSunday 27/05/1990 02:20 1.11 Grid co-ordinates291000/677570 1.10 Local AuthorityFalkirk 1.12/1.13 lst road identity. B810 1.8/1.19 2nd road identity 1.22 WeatherFine 1.21 Light conditionsDark/lights lit 1.20a Crossing(human)No Human control within 50m 1.20b Crossing(physical)No crossing facility within 50m	1.15 Speed limit	e c'way	
Contributory Factors	Participant	Confidence Did a police officer atten	
M-Value			
Accident Description V2 STATIONARY AT LOCUS WHEN V1 COLLIDED WITH REAR OF V2 N	COUNTED FOOTWAY AND DEMOLISHED 10 FEF	T OF WALL	
2 Vehicles		TOURADE.	
2.4 Veh ref no1			
2.17 Other vehicle2	2.16 First impactFront	(
2.5 Vehicle classCar 2.10 Junction locationNot at junction	2.12 Hit object in c'way. Parket	vehicle unlit	
2.9 Restricted location.On main carriageway	2.14 Hit object off c'way.Other	permanent object	
2.8 Movement from/toWest East	2.18 Parts damaged/ / 2.21 Driver genderMale	Front	
2.7 ManoeuvresGoing ahead right hand bend	2.22 Driver age23		
2.11 SkiddingYes 2.13 Left c'wayLeft c'way near-side	2.27 Driver postcode		
2.13 Left C'WayLeft C'Way near-side 2.6 TowingNo	2.24 Hit and RunNo		
2.28 Foreign vehicleNot foreign	2.23 Breath testNot re 2.29 Journey purpose	quested	
2.4 Veh ref no2	papooi		
2.17 Other vehicle1	2.16 First impactBack		
2.5 Vehicle classCar	2.12 Hit object in c'wayNone		
2.10 Junction locationNot at junction	2.14 Hit object off c'way.None		
2.9 Restricted location:On main carriageway	2.18 Parts damaged/ /	Back	
2.8 Movement from/toParked	2.21 Driver genderMale		
2.7 ManoeuvresParked 2.11 SkiddingNo	2.22 Driver age31		
2.13 Leit C'wayDid not leave c'way	2.27 Driver postcode 2.24 Hit and RunNo		
2.6 TowingNo	2.23 Breath testNot re	miested	
2.28 Foreign vehicleNot foreign	2.29 Journey purpose	quebled	
2 Casualties			
3.5 Cas ref no1	3.15 Car passengerNo		
3.6 Casualty classDriver or Rider 3.7 GenderMale	3.16 PSV passengerNo		
3.8 Age23	3.14 Seat belt usage	i i	
3.18 Casualty postcode	3.13 School pupil		
3.9 SeveritySlight	3.10 Pedestrian location. Not a p	edestrian	
3.4 Vehicle no1	3.11 Pedestrian movementNot a p	edestrian	
3.12 Ped DirectionNot a pedestrian	3.19 Roadworker injuredNo		
3.5 Cas ref no2 3.6 Casualty classDriver or Rider	3.15 Car passengerNo		
3.6 Casualty classDriver or Rider 3.7 GenderMale	3.16 PSV passengerNo		
.B Age31	3.14 Seat belt usage		
	3.13 School pupilOther		
.18 Casualty postcode	(3.19 School \	3.10 Pedestrian locationNot a pedestrian	
.18 Casualty postcode9 SeveritySlight	(3.19 School) 3.10 Pedestrian locationNot a p	edestrian	
3.18 Casualty postcode 3.9 SeveritySlight 3.4 Vehicle no2 3.12 Ped DirectionNot a pedestrian	(3.19 School) 3.10 Pedestrian locationNot a p 3.11 Pedestrian movementNot a p	edestrian edestrian	

${\tt B810}$ within ${\tt 75m}$ of direct access to Springbank Cottage

1.3 Accident Reference:111100067 Slight B810 Shieldhill Rodriveway to Reddir 1.7 Date & 1.9 TimeSunday 09/01/2011 21:40 1.11 Grid co-ordinates290930/677540 1.10 Local Authority	pad, Reddingmuirhead directly at the Accident 7 of 8 mg Rigg. 1.15 Speed limit			
	Yes			
Accident Description V1 was travelling east at locus when it skidded on black ice and veered onto the opposite side of the road in the direction of an electricity pole. The driver of V1 took evasive action causing V1 to skid and turn on it's side. 1 Vehicle				
2.4 Veh ref no	2.16 First impactNearside 2.12 Hit object in c'way.None 2.14 Hit object off c'way.None 2.18 Parts damaged/ 2.21 Driver genderMale 2.22 Driver age36 2.27 Driver postcode FK20DT 2.24 Hit and RunNo 2.23 Breath testNegative 2.29 Journey purpose			
1 Casualty				
3.5 Cas ref no1 3.6 Casualty classPassenger 3.7 GenderMale 3.8 Age15 3.18 Casualty postcode FK12EN 3.9 SeveritySlight 3.4 Vehicle no1 3.12 Ped DirectionNot a pedestrian	3.15 Car passengerFront 3.16 PSV passengerNo 3.14 Seat belt usage 3.13 School pupilOther- (3.19 School) 3.10 Pedestrian location.Not a pedestrian 3.11 Pedestrian movement.Not a pedestrian 3.12 Roadworker injuredNo			