

ESTATE MANAGEMENT – INSPECTION ANALYSIS FORM

Neighbourhood Patch: Banknock	Walkabout Area:	Walkabout Area Code:	Date:
	Glenview Avenue Auchincloch Drive	FK4	21/10/15
Officer Conducting Walkabout: CATH HARMON	Panel Leader:		
No. of Residents attending: 0	N/A		
Name of Councillor(s) attending: Cllr Blackwood, Cllr McCabe			
Others attending: Karen Laird, Gary Neill (Roads), David Frize (Community Safety Team)			

Mark generally satisfactory – generally unsatisfactory

	Satisfactory	Unsatisfactory	Text – Reasons for Scoring Unsatisfactory
Tenanted Visible gardens	X		
Common Closes	N/A	N/A	
Common Bin Stores	N/A	N/A	
Common Drying Areas	N/A	N/A	
Soft Landscape Areas	X		
Hard Landscaped Areas	X		
Play area(s)	X		
Overall Satisfactory/ Unsatisfactory	YES		
Other issues noted requiring attention / action			
<ul style="list-style-type: none"> Broken drain cover at roadside just outside 39 Auchincloch Drive – Gary Neill Overgrown hedge between Glenview Avenue and Auchincloch Drive, causing pedestrians to walk on roadside – Gary Neill 			Text - Agreed Action to Rectify <ul style="list-style-type: none"> Roads will repair broken drain Roads will investigate overgrown hedge (as per discussion with Gary Neill)

Signed Lead Officer – Cath Harmon

Signed Panel Leader _____

Dated – 21/10/15